



NFTAC

NATIONAL FIREBIRD and TRANS AM CLUB

TECHNICAL SECTIONS Volume II

Reprints from the 1998 thru 2007 NFTAC *EAGLE*

AVAILABLE ON USB FLASH DRIVE, ON CD, BY EMAIL AND IN PRINTED FORMATS

Volume I covering earlier publications and Volume III covering later publications
also available from the NFTAC

PUBLISHED BY THE NFTAC
5433 N. ASHLAND AVE., CHICAGO, IL 60640 U.S.A.
phone/text: 773-769-7166



email: info@firebirdtaclub.com
website: firebirdtaclub.com or www.firebirdtransamclub.com

NFTAC TECHNICAL SECTIONS VOLUME II

| <u>PUBLICATION</u> | <u>PAGE</u> |
|------------------------------|-------------|
| 1998 February | 10 |
| 1998 August | 15 |
| 1998 November | 23 |
| 1999 February | 25 |
| 1999 May | 30 |
| 1999 November | 39 |
| 2000 February | 43 |
| 2000 May | 49 |
| 2000 August | 55 |
| 2000 November | 60 |
| 2001 February | 63 |
| 2001 May | 67 |
| 2001 August | 70 |
| 2001 November | 73 |
| 2002 February | 78 |
| 2002 May | 83 |
| 2002 August | 88 |
| 2002 November | 93 |
| 2003 February | 97 |
| 2003 May | 100 |
| 2003 August | 107 |
| 2004 January | 114 |
| 2004 May | 119 |
| 2004 August | 123 |
| 2004 November | 130 |
| 2005 February | 134 |
| 2005 May | 138 |
| 2005 August | 142 |
| 2006 January | 144 |
| 2006 May | 146 |
| 2006 August | 148 |
| 2006 November | 150 |
| 2007 February | 154 |
| 2007 May | 158 |
| 2007 August | 160 |
| NFTAC Technical Services | 162 |
| NFTAC Store Order Form | 163 |
| NFTAC Membership Application | 164 |

NOTE: Please note the ads that may appear here are reproduced as they originally appeared in that issue and therefore may be several years old and are not to be relied on for prices or information.

Nothing may be reproduced in whole or in part without the express written consent of the publisher. The views of contributing writers are their own and not necessarily the views of the NFTAC. Readers are warned in following any advice given and no liability either express or implied is assumed by the advice or opinions given by individual contributors or the NFTAC.

ARTICLE INDEX

Publication references in which NFTAC publication the article originally appeared and the year; the page number it was on and if a Question and Answer (Q & A), its position on the page and page number in this issue.

| SUBJECT/ <u>ARTICLE</u> | ORIGINAL PUBLICATION | | PAGE NUMBER | |
|-------------------------------|----------------------|-------------|------------------|-------------------|
| | <u>ISSUE</u> | <u>PAGE</u> | <u>Q & A</u> | <u>THIS ISSUE</u> |
| Brakes | | | | |
| Adjusting rear discs | 2002 November | 33 | 3 | 95 |
| Brakes shaking steering wheel | 2000 May | 35 | 1 | 54 |
| Drum to disc brakes | 2002 November | 33 | 1 | 95 |
| Parking brake | 2002 November | 29 | 1 | 97 |
| Carburetion/Fuel System | | | | |
| '72 hood air scoop | 1999 May | 34 | | 35 |
| Aftermarket ram air system | 2000 August | 32 | 3 | 57 |
| Air intake tube | 2004 August | 32 | 1 | 126 |
| Airflow sensor screen | 2000 August | 29 | 6 | 56 |
| Black residue | 2006 August | 26 | 1 | 149 |
| Carb size | 2005 August | 22 | 1 | 143 |
| Cold air induction | 1998 November | 29 | 1 | 24 |
| Fried fuel pump | 2000 August | 29 | 3 | 56 |
| Fuel injector replacement | 2001 May | 32 | 1 | 68 |
| Gasoline vapor smell | 1999 May | 29 | 3 | 33 |
| Gas smell | 1998 November | 29 | 2 | 24 |
| Intake manifold/scoop | 2006 May | 22 | 2 | 146 |
| Ram air intake modification | 2007 August | 22 | 2 | 160 |
| Stalling | 2005 May | 23 | 1 | 139 |
| Stock throttle body | 2001 August | 32 | 1 | 70 |
| Surging | 2005 August | 21 | 5 | 142 |
| TPI Installation | 2001 February | 29 | 4 | 64 |
| Tripower installation | 2002 May | 29 | 4 | 84 |
| Wrong gas | 2000 November | 32 | 3 | 61 |
| Cooling and Heating Systems | | | | |
| '79 carb fit | 2000 May | 29 | 2 | 50 |
| AC recharging | 2003 August | 29 | 5 | 110 |
| AC removal | 2001 November | 28 | 2 | 73 |
| Cracked heater core | 2005 May | 23 | 3 | 139 |
| Downshift control cable | 2001 November | 28 | 3 | 73 |
| Cooling fans | 2005 August | 21 | 4 | 142 |
| Heater blower | 2002 February | 32 | 4 | 80 |
| Heater core leakage | 2003 February | 32 | 1 | 98 |
| Heater core replacement | 2000 May | 28 | 2 | 49 |
| Heater core removal | 2002 February | 28 | 1 | 78 |
| Low pressure AC port | 2002 February | 29 | 2 | 79 |
| Overheating | 1999 November | 25 | 6 | 39 |
| Overheating | 2001 February | 32 | | 65 |
| Overheats | 1999 November | 25 | 4 | 39 |
| Radiator hose collapse | 2004 November | 26 | 1 | 133 |
| Running hot | 2000 November | 29 | 2 | 60 |
| Running hot with AC on | 2004 January | 34 | | 118 |
| Temperature sending unit | 2003 August | 33 | 4 | 112 |

| SUBJECT/ <u>ARTICLE</u> | ORIGINAL PUBLICATION | | Q & A | PAGE NUMBER |
|--------------------------------|----------------------|-------------|-------|-------------------|
| | <u>ISSUE</u> | <u>PAGE</u> | | <u>THIS ISSUE</u> |
| Water temperature | 2000 August | 29 | 2 | 56 |
| Windshield defroster | 2003 August | 29 | 1 | 110 |
| Electrical | | | | |
| '06 & '97 headlight doors | 2000 August | 33 | | 58 |
| 2nd gear start switch | 2000 May | 28 | 1 | 49 |
| 32 amp alternator installation | 2003 May | 32 | 1 | 104 |
| 4th generation headlight fix | 2002 May | 33 | | 86 |
| '88 digital dash | 2003 May | 28 | 6 | 102 |
| Another headlight fix | 2002 May | 34 | | 92 |
| Computer checks | 1998 August | 29 | 2 | 19 |
| ESM reset | 2000 February | 29 | | 46 |
| Electrical system transfer | 1999 May | 32 | 2 | 34 |
| Firing order | 2002 February | 32 | 3 | 80 |
| Headlight door noise | 2002 November | 34 | | 96 |
| Headlights | 1999 February | 34 | | 28 |
| Headlights to stay open | 1999 November | 25 | 1 | 39 |
| Hidden headlight repair | 2000 May | 33 | | 52 |
| Horn relay | 2004 May | 33 | 4 | 121 |
| Instrument lights | 2002 November | 28 | 1 | 93 |
| Left headlight not opening | 2001 August | 34 | 4 | 72 |
| Low track light | 2000 November | 32 | 7 | 61 |
| Radio codes | 2003 May | 33 | | 105 |
| Radio head unit | 2004 August | 26 | 2 | 123 |
| Radio problem | 2003 May | 27 | 4 | 101 |
| Rear lights | 2004 January | 28 | 5 | 115 |
| Service engine light | 2001 February | 28 | 3 | 63 |
| SES light | 2005 May | 23 | 4 | 139 |
| Stock headlights on 3rd gen | 2004 January | 34 | | 118 |
| Turn signal bulb | 2002 February | 28 | 4 | 78 |
| Emission Controls | | | | |
| California smog equipment | 1999 February | 32 | 1 | 26 |
| Fault codes | 1998 August | 29 | 1 | 19 |
| Red catalytic converter | 2002 February | 28 | 3 | 78 |
| Engine/Mechanical | | | | |
| 4th generation headlight fix | 1999 November | 26 | | 40 |
| 403 Olds modifications | 2007 February | 21 | 1 | 154 |
| 350 & 400 engine difference | 2002 May | 29 | 3 | 84 |
| '67 original engine | 2000 May | 28 | 5 | 49 |
| '80 Trans Am with 400 | 2001 February | 29 | 5 | 64 |
| '81 TA engines | 2000 August | 29 | 5 | 56 |
| Belt replacement | 1999 February | 33 | 2 | 27 |
| Belt squealing | 2005 February | 22 | 4 | 134 |
| Bigger engine | 2001 May | 29 | 3 | 67 |
| Boring out | 2002 February | 32 | 1 | 80 |
| Cadillac engine | 2007 February | 22 | 2 | 155 |
| Engine hoist | 1999 May | 32 | 1 | 34 |
| Engine removal | 2002 February | 28 | 2 | 78 |
| Engine replacement | 2002 May | 34 | | 92 |

| SUBJECT/ ARTICLE | ORIGINAL PUBLICATION | | PAGE NUMBER | |
|-----------------------------|-----------------------------|-------------|--------------------|-------------------|
| | ISSUE | PAGE | Q & A | THIS ISSUE |
| Engine seal replacement | 2000 May | 32 | 1 | 51 |
| Engine setup | 1998 February | 28 | 2 | 10 |
| Engine swap | 1999 November | 25 | 7 | 39 |
| Engine swap #2 | 2001 May | 29 | 4 | 67 |
| Check engine light | 2000 August | 32 | 4 | 57 |
| Check engine light pt. 2 | 2001 May | 29 | | 67 |
| Horsepower buildup | 2002 February | 32 | 2 | 80 |
| Horsepower ratings | 2000 February | 26 | 4 | 43 |
| Idle stall | 2000 November | 32 | 1 | 61 |
| Insulating manifold heat | 2004 November | 23 | 2 | 131 |
| Manifold insulation | 1999 February | 33 | 1 | 27 |
| More horsepower | 2000 May | 28 | 3 | 49 |
| Motor mounts for 400 | 2002 May | 29 | 5 | 84 |
| Not starting | 2007 May | 22 | 2 | 158 |
| Olds 403 power | 2001 May | 32 | 3 | 68 |
| Olds 403 specs | 2004 August | 27 | 1 | 124 |
| Olds engine | 1999 November | 25 | 5 | 39 |
| Peak performance | 2001 May | 32 | 2 | 68 |
| Power steering fluid | 2003 August | 27 | 4 | 108 |
| Ram air V engine | 2000 August | 33 | | 58 |
| Rattling noise | 2000 February | 27 | 3 | 44 |
| RPM surge | 2001 August | 33 | 2 | 71 |
| Running rough | 2001 February | 28 | 1 | 63 |
| Supercharger | 2002 November | 32 | 4 | 94 |
| Starting problems | 2001 February | 29 | 1 | 64 |
| Vortec supercharger | 2000 November | 33 | | 62 |
| Ticking sound | 1999 May | 29 | 2 | 33 |
| Exhaust | | | | |
| Aftermarket headers | 1999 February | 35 | 1 | 29 |
| Best Cat-Back exhaust | 2002 February | 29 | 3 | 79 |
| Dual exhaust | 2003 February | 32 | 2 | 98 |
| Edelbrock manifold | 2004 January | 27 | 5 | 114 |
| Edelbrock performer | 2001 August | 32 | 4 | 70 |
| Exhaust manifold bolts | 2002 November | 32 | 2 | 94 |
| Exhaust replacement | 2003 August | 34 | | 113 |
| Exhaust system replacement | 2004 May | 28 | 4 | 119 |
| Flowmaster | 2004 January | 33 | 2 | 117 |
| Flowmaster exhaust | 2002 August | 28 | 3 | 88 |
| Headers | 2002 February | 33 | | 81 |
| Headers for a 301 | 2004 May | 28 | 1 | 119 |
| Manifolds | 2006 August | 26 | 3 | 149 |
| Muscle car sound | 2005 August | 21 | 2 | 142 |
| Ram Air III exhaust | 2001 February | 29 | 2 | 64 |
| Exterior/Body | | | | |
| 400 hood | 2006 May | 22 | 1 | 146 |
| '78 Formula t-tops | 2000 February | 27 | 1 | 44 |
| '79 decal set | 2000 August | 32 | 2 | 57 |
| '92 model year paint | 2000 August | 29 | 1 | 56 |
| American hatch t-tops | 2006 November | 21 | 3 | 150 |

| SUBJECT/ ARTICLE | ORIGINAL PUBLICATION | | PAGE NUMBER | |
|-------------------------------|-----------------------------|-------------|--------------------|-------------------|
| | ISSUE | PAGE | Q & A | THIS ISSUE |
| Bumper emblem | 2000 February | 26 | 1 | 43 |
| Eagle decal | 2005 May | 25 | 1 | 140 |
| Fiberglass fenders | 2005 May | 22 | 1 | 138 |
| Ground effects | 2007 May | 22 | 1 | 158 |
| GTA emblem | 2007 February | 26 | 3 | 156 |
| Precut striping | 2000 May | 29 | 1 | 50 |
| Rear quarter replacement | 2000 November | 32 | 4 | 61 |
| Rear spoiler replacement | 2005 August | 22 | 2 | 143 |
| Shaker hood scoops | 2000 November | 29 | 1 | 60 |
| Spoilers cracking | 2001 May | 29 | 1 | 67 |
| T-top crack | 2002 February | 29 | 4 | 79 |
| T-top seals | 2000 August | 28 | 3 | 55 |
| Weather-stripping | 2002 February | 29 | 1 | 79 |
| Gauges | | | | |
| Autometer gauges | 2005 February | 22 | 1 | 134 |
| Gauge Dial repair | 1999 November | 25 | 5 | 39 |
| Generator light | 2002 May | 32 | 4 | 85 |
| General | | | | |
| 14 second car | 2001 August | 34 | 1 | 72 |
| 5 Questions | 1999 February | 29 | 4 | 25 |
| '70 1/2 value | 2000 February | 26 | 3 | 43 |
| '78 Redbird | 2003 May | 26 | 1 | 100 |
| '80 pace car | 2002 February | 32 | 5 | 80 |
| '99 Firehawk | 2000 November | 33 | 1 | 62 |
| Acceleration increase | 2001 August | 34 | 5 | 72 |
| Bat out of hell | 2001 November | 28 | 1 | 73 |
| Car storage | 1998 February | 33 | | 12 |
| Differences in '70 to '73 TAs | 1998 August | 32 | | 20 |
| F in F-body | 2000 August | 33 | | 58 |
| First TA production date | 2003 May | 28 | 1 | 102 |
| Make '93 faster | 2000 February | 26 | 2 | 43 |
| NASCAR stickers | 2005 February | 26 | 4 | 136 |
| Performance chips | 2000 August | 33 | | 58 |
| Performance hints | 2002 February | 33 | | 81 |
| Performance testing | 1999 February | 32 | 2 | 26 |
| Power steering leak | 2002 February | 29 | 5 | 79 |
| Power to '75 Trans Am | 2006 August | 22 | 1 | 148 |
| Power to wheels | 2006 January | 22 | 1 | 144 |
| Research history of car | 2005 February | 23 | | 135 |
| Restoration | 1998 February | 28 | 1 | 10 |
| Rocket boost | 2003 May | 33 | | 105 |
| Rollover ratings | 2000 February | 28 | | 45 |
| Service manual | 2002 May | 28 | 2 | 83 |
| Setting timing | 2001 November | 29 | | 74 |
| Stated Value Insurance | 1998 August | 16 | | 15 |
| Trans Am from Firebird | 2005 August | 21 | 1 | 142 |
| Turbo S.E. difference | 2002 May | 29 | 1 | 84 |
| Windshield washer | 2002 February | 33 | | 81 |
| Winter storage tips | 2001 November | 29 | | 74 |

| SUBJECT/ <u>ARTICLE</u> | ORIGINAL PUBLICATION | | Q & A | PAGE NUMBER |
|-----------------------------|----------------------|-------------|-------|-------------------|
| | <u>ISSUE</u> | <u>PAGE</u> | | <u>THIS ISSUE</u> |
| Windshield washer | 2002 February | 34 | | 82 |
| Y-82 meaning | 2007 August | 22 | 1 | 160 |
| Interior | | | | |
| Back window removal | 2005 May | 23 | 2 | 139 |
| Bucket seat replacement | 2002 May | 28 | 1 | 83 |
| Console replacement | 2007 February | 29 | 2 | 157 |
| Cracked dash fixing | 2002 November | 34 | | 96 |
| Door alignment | 2004 May | 34 | | 122 |
| Headliner removal | 2003 August | 33 | 1 | 112 |
| Hinges | 2005 February | 22 | 2 | 134 |
| Interior upgrade | 2002 November | 34 | | 96 |
| Loose windows | 1999 November | 25 | 2 | 39 |
| Parchment seat covers | 2005 May | 23 | 5 | 139 |
| Part Changeability | 2001 February | 28 | 2 | 63 |
| Rear deck replacement | 2005 February | 26 | 2 | 136 |
| Seat belt guide removal | 2002 May | 29 | 2 | 84 |
| Seat color | 2006 November | 22 | 1 | 151 |
| Seat covers | 2006 November | 21 | 1 | 150 |
| Steering wheel emblem | 2006 November | 26 | 1 | 152 |
| Steering wheel removal | 2002 February | 34 | | 82 |
| Trunk release | 2004 August | 26 | 1 | 123 |
| Window relay | 1998 November | 28 | 2 | 23 |
| Numbers/Identification | | | | |
| Decode 4th generation VIN | 1998 February | 25 | | 14 |
| GM Vin Digit Identification | 2000 May | 35 | | 54 |
| Vin Number Breakdown | 1999 November | 28 | | 42 |
| Vin Number Breakdown pt. 2 | 2000 February | 32 | | 47 |
| Oil/Lubrication | | | | |
| The Dirt on oil | 1999 May | 24 | | 30 |
| Oil changes | 2004 August | 26 | 3 | 123 |
| Oil type | 2001 August | 33 | 1 | 71 |
| Posi oil | 2005 August | 22 | 3 | 143 |
| Synthetic oils | 2006 August | 26 | 2 | 149 |
| Suspension/Handling | | | | |
| Coil spring replacement | 2000 February | 27 | 2 | 44 |
| Limited slip additive | 1999 May | 29 | 1 | 33 |
| Lowering a 2nd generation | 2004 May | 34 | | 122 |
| Rack and pinion | 2001 August | 32 | 2 | 70 |
| Shocks | 2007 February | 26 | 1 | 156 |
| Spring spacers | 2006 November | 21 | 2 | 150 |
| Suspension improvements | 2005 August | 21 | 3 | 142 |
| Stock Auburn gear | 2001 August | 32 | 3 | 70 |
| Thunking noise | 2001 May | 29 | 2 | 67 |
| Vibration | 2002 May | 28 | 5 | 83 |
| Vibration on 4th generation | 2000 November | 33 | | 62 |
| Vibration problem | 2002 May | 34 | | 92 |
| WS-6 first year | 2000 August | 32 | 1 | 57 |

| SUBJECT/ ARTICLE | ORIGINAL PUBLICATION | | PAGE NUMBER | |
|--|-----------------------------|-------------|--------------------|-------------------|
| | ISSUE | PAGE | Q & A | THIS ISSUE |
| WS-6 package | 2001 August | 32 | 5 | 70 |
| WS-7 handling package | 2003 August | 34 | | 113 |
| WS-7 suspension | 2002 May | 28 | 3 | 83 |
| Tires/Wheels | | | | |
| '70 TA wheel sizes | 2002 May | 29 | 7 | 84 |
| 8 inch rims | 2003 May | 28 | 5 | 102 |
| '92 wheels | 2001 February | 33 | 1 | 66 |
| Center caps | 2002 November | 32 | 1 | 94 |
| Long shank lug nuts | 1998 November | 28 | 1 | 23 |
| Restoring wheels | 1998 February | 35 | | 14 |
| Refinish rims | 2002 May | 33 | 2 | 91 |
| Restoring wheels | 004 August | 34 | | 128 |
| Tire rotation | 2000 May | 33 | | 52 |
| Tire replacement | 2000 August | 28 | 1 | 55 |
| Tire size | 2004 August | 34 | | 128 |
| Tires | 1999 February | 34 | | 28 |
| Tires pt. 2 | 2004 November | 27 | | 133 |
| Transmission/Clutch/Drive Train | | | | |
| 4.10 rear end | 2002 May | 32 | 2 | 90 |
| 700R4 transmission | 2000 November | 32 | 5 | 61 |
| Clunking noise | 2000 May | 28 | 5 | 49 |
| Clutch replacement | 2000 November | 33 | 2 | 62 |
| Gears | 2006 May | 26 | 1 | 147 |
| Hurst usage | 2001 August | 33 | 3 | 71 |
| Powerglide transmission | 2007 February | 21 | 2 | 154 |
| Transmission choice | 2002 February | 33 | | 81 |
| Transmission leakage | 2006 August | 22 | 2 | 148 |
| Transmission service | 2000 May | 33 | | 52 |
| Transmission swap | 2001 May | 33 | | 69 |
| Transmission tuning | 1998 August | 28 | 1 | 18 |
| Transmission tuning pt. 2 | 2004 August | 33 | 1 | 127 |



NATIONAL FIREBIRD and TRANS AM CLUB

TECHNICAL SECTIONS Volume III

Reprints from the 2008 thru 2022 NFTAC *EAGLE*

AVAILABLE ON USB FLASH DRIVE, ON CD, BY EMAIL AND IN PRINTED FORMATS

Volume I and Volume II covering publications also available from the NFTAC

PUBLISHED BY THE NFTAC
5433 N. ASHLAND AVE., CHICAGO, IL 60640 U.S.A.
phone/text: 773-769-7166



email: info@firebirdtaclub.com
website: firebirdtaclub.com or www.firebirdtransamclub.com

NFTAC TECHNICAL SECTIONS VOLUME III

| <u>PUBLICATION</u> | <u>PAGE</u> | <u>PUBLICATION</u> | <u>PAGE</u> |
|--------------------|-------------|--------------------|-------------|
| 2008 January | 13 | 2019 November | 122 |
| 2008 May | 16 | 2020 February | 124 |
| 2008 August | 18 | 2020 May | 126 |
| 2008 November | 21 | 2020 August | 128 |
| 2009 February | 24 | 2020 November | 130 |
| 2009 May | 27 | 2021 February | 132 |
| 2009 August | 27 | 2021 May | 134 |
| 2010 January | 35 | 2021 August | 136 |
| 2010 May | 38 | 2021 November | 138 |
| 2010 August | 41 | 2022 February | 140 |
| 2010 November | 44 | 2022 May | 142 |
| 2011 February | 47 | 2022 August | 144 |
| 2011 May | 49 | 2022 November | 146 |
| 2011 August | 52 | | |
| 2011 November | 54 | | |
| 2012 February | 56 | | |
| 2012 May | 59 | | |
| 2012 August | 62 | | |
| 2012 November | 64 | | |
| 2013 February | 66 | | |
| 2013 May | 68 | | |
| 2013 August | 70 | | |
| 2013 November | 73 | | |
| 2014 February | 76 | | |
| 2014 May | 74 | | |
| 2014 August | 80 | | |
| 2014 November | 82 | | |
| 2015 February | 84 | | |
| 2015 May | 86 | | |
| 2015 August | 88 | | |
| 2015 November | 90 | | |
| 2016 February | 92 | | |
| 2016 May | 90 | | |
| 2016 August | 96 | | |
| 2016 November | 98 | | |
| 2017 February | 100 | | |
| 2017 May | 102 | | |
| 2017 August | 104 | | |
| 2017 November | 106 | | |
| 2018 February | 108 | | |
| 2018 May | 110 | | |
| 2018 August | 112 | | |
| 2018 November | 114 | | |
| 2019 February | 116 | | |
| 2019 May | 118 | | |
| 2019 August | 120 | | |

NOTE: Please note the ads that may appear here are reproduced as they originally appeared in that issue and therefore may be several years old and are not to be relied on for prices or information.

Nothing may be reproduced in whole or in part without the express written consent of the publisher. The views of contributing writers are their own and not necessarily the views of the NFTAC. Readers are warned in following any advice given and no liability either express or implied is assumed by the advice or opinions given by individual contributors or the NFTAC.

ARTICLE INDEX

Publication references in which NFTAC publication the article originally appeared and the year; the page number it was on and if a Question and Answer (Q & A), its position on the page and page number in this issue.

| SUBJECT/ <u>ARTICLE</u> | ORIGINAL PUBLICATION | | | PAGE NUMBER |
|--------------------------------|----------------------|-------------|------------------|-------------------|
| | <u>ISSUE</u> | <u>PAGE</u> | <u>Q & A</u> | <u>THIS ISSUE</u> |
| BRAKES | | | | |
| Brake lines | 2018 November | 24 | 3 | 114 |
| Brakes pulsing | 2016 May | 23 | 1 | 94 |
| Caliper sizes | 2008 August | 21 | 3 | 18 |
| Disc brake conversion | 2009 May | 26 | 2 | 25 |
| Disc brakes on GTAs | 2022 May | 25 | 3 | 143 |
| Rear brakes not working | 2016 August | 24 | 1 | 96 |
| Rear drum to disc conversion | 2015 August | 26 | | 89 |
| CARBURETION/FUEL SYSTEM | | | | |
| 305 to 350 carburetor | 2014 February | 26 | 1 | 77 |
| Car shutting off | 2013 May | 26 | 2 | 68 |
| Carb problems | 2009 May | 26 | 4 | 33 |
| Carb size | 2011 November | 23 | 3 | 54 |
| Carb suggestions | 2021 February | 25 | 4 | 133 |
| Carburetor throttle | 2008 November | 26 | 2 | 22 |
| Carburetor troubleshooting | 2010 January | 27 | 1 | 37 |
| Cold air intake | 2019 August | 25 | 3 | 121 |
| Edelbrock carb | 2009 August | 21 | 1 | 31 |
| Edelbrock performer intake | 2020 November | 25 | 3 | 131 |
| Edelbrock performer package | 2014 November | 26 | 1 | 83 |
| Fuel Dilemma | 2022 February | 24 | 2 | 140 |
| Fuel line removal | 2020 February | 25 | 1 | 125 |
| Fuel pressure regulator | 2019 August | 24 | 1 | 120 |
| Fuel pump and no gas | 2012 February | 23 | 2 | 56 |
| Fuel pump circuit - code 54 | 2022 May | 24 | 1 | 142 |
| Fuel pump problems | 2013 August | 23 | 2 | 70 |
| Fuel pump relay | 2016 November | 24 | 2 | 98 |
| Fuel pump relay wire | 2016 November | 25 | 1 | 99 |
| Fuel pump replacement | 2022 February | 25 | 6 | 141 |
| Gas incorrect | 2013 August | 26 | 3 | 71 |
| Gas odor | 2021 February | 25 | 5 | 133 |
| Gas tank replacement | 2022 November | 26 | 1 | 147 |
| No throttle response | 2009 May | 26 | 2 | 29 |
| Shaker cost | 2018 May | 24 | 3 | 110 |
| T.P. I. throttle | 2013 November | 26 | 4 | 74 |
| COOLING/HEATING SYSTEM | | | | |
| A/C evaporate condensate line | 2010 January | 26 | 2 | 36 |
| A/C and heat duct pipes | 2015 May | 26 | 4 | 87 |
| Coolant flow sensor | 2012 May | 26 | 5 | 60 |
| Coolant hose leak | 2010 November | 26 | 1 | 45 |
| Coolant light | 2017 August | 25 | 1 | 105 |
| Coolant lights | 2012 May | 26 | 4 | 60 |

| SUBJECT/ ARTICLE | ORIGINAL PUBLICATION | | | PAGE NUMBER |
|-----------------------------|-----------------------------|-------------|------------------|--------------------|
| | ISSUE | PAGE | Q & A | THIS ISSUE |
| Heater control vacuum | 2009 August | 26 | 2 | 33 |
| Heater core replacement | 2011 February | 22 | 1 | 47 |
| Heater core replacing | 2011 November | 22 | 2 | 54 |
| Heater not working | 2014 May | 26 | 3 | 79 |
| Overheating | 2013 November | 27 | | 75 |
| Overheating caused by fan | 2016 August | 25 | 1 | 97 |
| Shaker hood hole aligned | 2017 November | 24 | 1 | 106 |
| Thermostat | 2019 August | 24 | 4 | 120 |

ELECTRICAL

| | | | | |
|----------------------------------|---------------|----|---|-----|
| Alternators being replaced often | 2020 November | 24 | 3 | 130 |
| Battery runs down | 2008 August | 21 | 4 | 18 |
| Blinkers not working | 2015 August | 23 | 2 | 88 |
| Body control module | 2020 August | 25 | 3 | 129 |
| Brake light not working | 2020 May | 24 | 2 | 126 |
| Bulb replacement | 2022 August | 26 | 3 | 145 |
| Chip question | 2017 February | 24 | 4 | 100 |
| Computer out | 2013 August | 26 | 1 | 71 |
| Delco alternator number | 2017 May | 25 | 2 | 102 |
| Distributor module | 2021 August | 25 | 4 | 137 |
| Electric schematic diagram | 2008 May | 21 | 1 | 16 |
| Electrical connections | 2021 May | 25 | 2 | 135 |
| Electrical problems | 2008 November | 27 | 1 | 22 |
| Exterior lights | 2010 November | 23 | 1 | 44 |
| Fan switch | 2013 May | 26 | 3 | 68 |
| Fuse box power | 2010 August | 26 | 3 | 42 |
| Headlight grinding noise | 2021 November | 25 | 5 | 139 |
| Headlight motor | 2021 February | 25 | 3 | 133 |
| Headlight not going up | 2020 November | 25 | 1 | 131 |
| Headlights not opening | 2018 February | 24 | 3 | 108 |
| HID headlight installation | 2012 May | 26 | 1 | 60 |
| Ignition switch | 2020 August | 24 | 1 | 128 |
| No spark | 2021 August | 24 | 1 | 136 |
| Not starting | 2015 August | 23 | 1 | 88 |
| Power antenna replacement | 2022 November | 25 | 1 | 146 |
| Radio repair | 2022 August | 26 | 1 | 145 |
| Rear turn signal | 2022 August | 26 | 5 | 145 |
| Speakers blown | 2022 May | 24 | 2 | 142 |
| Speaker replacement | 2022 February | 25 | 3 | 141 |
| Speedometer not working | 2020 August | 25 | 2 | 129 |
| Stock headlights | 2019 November | 25 | 1 | 123 |
| Vats system | 2016 November | 24 | 3 | 98 |
| Windshield antenna | 2018 February | 24 | 2 | 108 |
| Wiring harness swap | 2010 August | 23 | 3 | 41 |
| Wiring harness source | 2012 May | 23 | 1 | 59 |
| Wiring harness swap | 2010 August | 23 | 3 | 41 |

| SUBJECT/ ARTICLE | ORIGINAL PUBLICATION | | | PAGE NUMBER |
|---------------------------------|-----------------------------|-------------|------------------|--------------------|
| | ISSUE | PAGE | Q & A | THIS ISSUE |
| EMISSION CONTROLS | | | | |
| EGR flow code | 2012 August | 26 | 2 | 62 |
| Emission conversion | 2012 August | 26 | 3 | 62 |
| Filler cap tightness | 2012 May | 26 | 2 | 60 |
| Mass airflow sensor | 2010 August | 23 | 1 | 41 |
| Mass airflow sensor code | 2010 November | 26 | 6 | 45 |
| Mass airflow sensor removal | 2012 February | 26 | 3 | 57 |
| Mass airflow sensor replacement | 2014 August | 23 | 2 | 80 |
| Oxygen sensor | 2012 February | 26 | 6 | 57 |
| Oxygen sensor code | 2012 August | 26 | 1 | 62 |
| ENGINE/MECHANICAL | | | | |
| 5.0 LT TPI engine | 2018 February | 25 | 1 | 109 |
| 205 engine replacement | 2017 November | 25 | 1 | 107 |
| 400 version in '78 Formula | 2011 May | 27 | 1 | 51 |
| 403 rebuild | 2015 February | 26 | 3 | 85 |
| 1981 T/A engines | 2012 February | 26 | 2 | 57 |
| AC bypass | 2018 May | 24 | 2 | 110 |
| Belt noises | 2009 February | 26 | 1 | 25 |
| Block and head castings | 2016 February | 23 | 2 | 92 |
| Block value | 2011 February | 22 | 2 | 47 |
| Car not starting | 2013 November | 26 | 2 | 74 |
| Check engine light | 2010 May | 26 | 1 | 39 |
| Compression | 2013 May | 26 | 1 | 68 |
| Cruise control operational | 2010 January | 27 | 2 | 37 |
| Cylinder misfire | 2019 November | 25 | 2 | 123 |
| Engine block seal | 2011 November | 23 | 4 | 55 |
| Engine knock | 2015 May | 26 | 1 | 87 |
| Engine missing | 2018 August | 24 | 1 | 112 |
| Engine surge | 2015 February | 26 | 1 | 85 |
| Engine swap in '83 Firebird | 2014 February | 23 | 3 | 76 |
| Engine will not start | 2013 February | 26 | 1 | 66 |
| Gasket set | 2017 May | 25 | 3 | 102 |
| Head gasket sealing | 2020 May | 24 | 3 | 126 |
| High torque starter | 2013 May | 27 | 2 | 69 |
| Horsepower adding | 2011 November | 22 | 3 | 54 |
| Horsepower increase with 305 | 2018 May | 24 | 1 | 110 |
| Horsepower increase | 2015 May | 23 | 3 | 86 |
| Horsepower ratings | 2011 May | 23 | 6 | 50 |
| Idle high | 2021 February | 25 | 1 | 133 |
| Idle speed | 2010 January | 26 | 1 | 36 |
| Ignition timing | 2015 May | 23 | 1 | 86 |
| Injector replacement | 2012 November | 23 | 2 | 64 |
| Long tube headers | 2020 August | 24 | 2 | 128 |
| LT1 rebuild | 2014 August | 26 | 3 | 81 |
| Misfire | 2012 May | 23 | 2 | 59 |
| More power from 403 | 2014 February | 26 | 4 | 77 |

| SUBJECT/ ARTICLE | ORIGINAL PUBLICATION | | | PAGE NUMBER |
|---------------------------------|-----------------------------|-------------|------------------|--------------------|
| | ISSUE | PAGE | Q & A | THIS ISSUE |
| Motor replacement on '89 | 2021 May | 24 | 3 | 134 |
| Oil pan | 2019 August | 25 | 4 | 121 |
| Oil pressure not constant | 2020 November | 25 | 2 | 131 |
| Oil recommendation | 2018 November | 24 | 2 | 114 |
| Oil usage | 2021 May | 24 | 1 | 134 |
| Optispark distributor | 2017 February | 24 | 2 | 100 |
| Original engine in '67 Firebird | 2011 November | 23 | 1 | 55 |
| PCM flashing | 2012 November | 23 | 1 | 64 |
| Peak performance in '78 WS6 | 2014 February | 26 | 3 | 77 |
| Power steering cooler | 2021 August | 25 | 2 | 137 |
| Power steering leak | 2018 August | 24 | 3 | 112 |
| PVC system | 2018 Februray | 24 | 1 | 108 |
| Ram air V engine | 2012 February | 27 | | 58 |
| Running rough | 2013 November | 23 | 1 | 73 |
| Service engine light | 2013 November | 26 | 1 | 74 |
| Spark plug problems | 2018 August | 24 | 2 | 112 |
| Starter working out of car | 2020 February | 24 | 3 | 124 |
| Starting problem | 2016 November | 24 | 1 | 98 |
| Starting problem #2 | 2019 August | 25 | 2 | 121 |
| Starting problems #3 | 2021 February | 25 | 2 | 133 |
| Stroker engine meaning | 2020 May | 24 | 1 | 126 |
| Timing | 2015 May | 23 | 1 | 86 |
| Timing chain | 2022 February | 25 | 4 | 141 |
| Timing setting | 2016 February | 26 | | 93 |
| Tuning new engine | 2010 January | 23 | 2 | 35 |
| Turbo, carb, ignition | 2013 August | 26 | 2 | 71 |
| Turbo swap | 2019 August | 24 | 2 | 120 |
| Vacuum acuator | 2021 August | 25 | 3 | 137 |
| Vacuum advance hookup | 2020 August | 25 | 1 | 129 |
| Vortec heads | 2014 May | 26 | 4 | 79 |
| Vortec supercharger | 2013 August | 27 | | 62 |
| WS package for 1984 | 2014 November | 23 | 1 | 82 |
| WS-6 performance options | 2012 February | 26 | 4 | 57 |
| EXHAUST | | | | |
| 40 series muffler | 2018 May | 25 | 2 | 111 |
| Exhaust sound | 2014 August | 26 | 2 | 81 |
| Header wrap | 2014 May | 23 | 2 | 78 |
| Headers | 2013 February | 26 | 2 | 66 |
| Headers in '87 Firebird | 2014 May | 26 | 1 | 79 |
| RA III exhaust | 2013 November | 26 | 3 | 74 |
| Resonator | 2018 August | 25 | 1 | 113 |
| Straight pipe exhaust | 2014 May | 26 | 2 | 79 |
| EXTERIOR/BODY | | | | |
| '96 and '97 headlight doors | 2012 February | 27 | | 57 |
| Aero kit | 2013 November | 23 | 2 | 73 |

| SUBJECT/ ARTICLE | ORIGINAL PUBLICATION | | | PAGE NUMBER |
|-------------------------------|-----------------------------|-------------|------------------|--------------------|
| | ISSUE | PAGE | Q & A | THIS ISSUE |
| Bird decal | 2021 November | 24 | 2 | 138 |
| Bird decal adhesive | 2014 May | 23 | 3 | 78 |
| Body shell | 2008 January | 22 | 1 | 14 |
| Bumper emblems | 2011 May | 23 | 3 | 50 |
| Car cover | 2010 November | 26 | 2 | 45 |
| Center console removal | 2019 February | 26 | 1 | 116 |
| Clear coat engine compartment | 2022 August | 26 | 2 | 145 |
| Convertible top/seals | 2011 May | 23 | 1 | 50 |
| Doors for '98 Firebird | 2016 May | 26 | 1 | 95 |
| Door locks | 2021 August | 24 | 2 | 136 |
| Door sagging | 2022 February | 25 | 1 | 141 |
| Engine bay appearance | 2020 November | 24 | 2 | 13 |
| Exterior trim colors | 2009 February | 22 | 1 | 24 |
| Fender replacement | 2009 May | 21 | 1 | 27 |
| Front end '73 to '77 | 2021 February | 25 | 2 | 132 |
| Hatch hanging | 2022 February | 25 | 2 | 141 |
| Hatch mechanism | 2022 August | 25 | 1 | 144 |
| Headlights flipping open | 2012 February | 23 | 1 | 56 |
| Headlights manually opening | 2008 May | 22 | 3 | 17 |
| Headlight height adjustment | 2009 August | 27 | 3 | 34 |
| Headlight not opening | 2015 May | 23 | 2 | 86 |
| Headlight staying open | 2020 February | 24 | 1 | 124 |
| Hood decal | 2012 February | 26 | 5 | 57 |
| Hood scoop flipper | 2020 August | 24 | 3 | 128 |
| Hood scoop function | 2008 May | 21 | 2 | 16 |
| Items to get great paint | 2015 November | 26 | | 91 |
| Key replacement | 2008 August | 21 | 2 | 18 |
| Lower front end | 2021 February | 24 | 4 | 132 |
| Nose and grille swap | 2008 August | 26 | 2 | 20 |
| Original color and value | 2009 May | 22 | 2 | 28 |
| Original chrome shine | 2010 January | 23 | 1 | 35 |
| Original Paint Showing | 2020 February | 24 | 2 | 124 |
| Paint bubbles | 2015 August | 26 | | 89 |
| Paint bubbling | 2014 August | 23 | 1 | 80 |
| Paint code | 2013 August | 23 | 1 | 70 |
| Paint codes for interior | 2022 May | 25 | 4 | 142 |
| Personal preferences | 2014 May | 26 | 7 | 79 |
| Pop up headlights | 2008 November | 26 | 3 | 22 |
| Primers, all about | 2010 May | 27 | | 40 |
| Primer factory colors | 2010 August | 27 | | 43 |
| Ram air hoods | 2020 May | 25 | 2 | 127 |
| Rear quarter repair | 2013 August | 26 | 4 | 71 |
| Rust repair | 2022 May | 25 | 1 | 143 |
| Sail panel bubbling | 2019 February | 27 | 1 | 117 |
| Scoop seal | 2009 May | 27 | 1 | 30 |
| Sequential tail lights | 2013 February | 27 | | 67 |
| Spoiler cracking | 2014 February | 23 | 1 | 76 |